

HISTORIC RESOURCES SURVEY FORM

1. Identification

County Hamison City Marshall
 Current name Weisman-Hirsch-Beil Historic name Weisman-Hirsch
 Address 313 S. Washington
 Owner/address Gail Beil — 313 S. Washington

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: NR NR District (is property contributing? Yes No) RTHL HTC SAL Local Other

Recorded by: Natalie Bach Date recorded: _____

General architectural description ^{2-story} Queen Anne w/several gables, 2 brick chimneys, Brick foundation

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed Other Small house

Archeological evidence of outbuildings, specify _____

Landscape/site features:

Sidewalks Terracing Drives Well/cistern Gardens Other _____

2. Architectural Description

Stylistic Influence(s):

- | | | | | |
|--|--|---|---|---|
| <input type="checkbox"/> Log Traditional | <input type="checkbox"/> Shingle | <input type="checkbox"/> Gothic Revival | <input type="checkbox"/> Pueblo Revival | <input type="checkbox"/> International |
| <input type="checkbox"/> Greek Revival | <input type="checkbox"/> Romanesque Revival | <input type="checkbox"/> Tudor Revival | <input type="checkbox"/> Spanish Colonial | <input type="checkbox"/> Post-war Modern |
| <input type="checkbox"/> Italianate | <input type="checkbox"/> Folk Victorian | <input type="checkbox"/> Neo-Classical | <input type="checkbox"/> Prairie | <input type="checkbox"/> Ranch Style |
| <input type="checkbox"/> Second Empire | <input type="checkbox"/> Colonial Revival | <input type="checkbox"/> Beaux Arts | <input type="checkbox"/> Craftsman | <input type="checkbox"/> Commercial Style |
| <input type="checkbox"/> Eastlake | <input type="checkbox"/> Renaissance Revival | <input type="checkbox"/> Mission | <input type="checkbox"/> Art Deco | <input type="checkbox"/> No Style |
| <input checked="" type="checkbox"/> Queen Anne | <input type="checkbox"/> Exotic Revival | <input type="checkbox"/> Monterey | <input type="checkbox"/> Moderne | <input type="checkbox"/> Other _____ |

Structural Details:

<p>Roof Type:</p> <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Hipped <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Flat w/parapet <input checked="" type="checkbox"/> Dormers: <input checked="" type="checkbox"/> gable <input type="checkbox"/> hipped <input type="checkbox"/> shed <input type="checkbox"/> Other _____ <p>Roof Materials:</p> <input type="checkbox"/> Wood shingles <input type="checkbox"/> Tile <input checked="" type="checkbox"/> Composition shingles <input type="checkbox"/> Metal _____ <input type="checkbox"/> Other _____ <p>Construction:</p> <input checked="" type="checkbox"/> Frame <input type="checkbox"/> Adobe <input type="checkbox"/> Solid brick <input type="checkbox"/> Solid stone <input type="checkbox"/> Other _____	<p>Wall Facade:</p> <p>_____ Number of bays</p> <input type="checkbox"/> Stucco <input type="checkbox"/> Stone <input type="checkbox"/> Brick <input checked="" type="checkbox"/> Wood shingle <input type="checkbox"/> Log <input type="checkbox"/> Terra Cotta <input type="checkbox"/> Metal <input type="checkbox"/> Siding, type _____ <input type="checkbox"/> Fieldstone veneer <input type="checkbox"/> Awning(s) <input type="checkbox"/> Other _____ <p>Chimneys:</p> <p><u>2</u> Specify number(s)</p> <input type="checkbox"/> Interior <input type="checkbox"/> Exterior <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Stone <input type="checkbox"/> With corbelled caps <input type="checkbox"/> Stuccoed <input type="checkbox"/> Other _____	<p>Windows:</p> <input type="checkbox"/> Fixed <input type="checkbox"/> Wood sash <input checked="" type="checkbox"/> Double hung <input type="checkbox"/> Casement <input type="checkbox"/> Aluminum sash <input type="checkbox"/> Decorative screenwork <input type="checkbox"/> Other _____ <p>Doors:</p> <input type="checkbox"/> Single-door primary entrance <input checked="" type="checkbox"/> Double-door primary entrance <input type="checkbox"/> With transom <input checked="" type="checkbox"/> With sidelights <input type="checkbox"/> Other _____ <p>Porches:</p> <input type="checkbox"/> Shed roof <input type="checkbox"/> Hipped roof <input checked="" type="checkbox"/> Gable roof <input type="checkbox"/> Inset <input type="checkbox"/> Wood posts <input type="checkbox"/> Brick piers <input type="checkbox"/> Box columns	<p>Plan:</p> <input type="checkbox"/> L-plan <input type="checkbox"/> 2-room <input type="checkbox"/> T-plan <input type="checkbox"/> Open <input type="checkbox"/> Modified L-plan <input type="checkbox"/> Center passage <input type="checkbox"/> Bungalow <input type="checkbox"/> Shotgun <input type="checkbox"/> Irregular <input type="checkbox"/> Four Square <input type="checkbox"/> Rectangular <input type="checkbox"/> Other _____ <p>Foundation:</p> <input type="checkbox"/> Slab <input checked="" type="checkbox"/> Pier and beam <input type="checkbox"/> Perimeter wall <input type="checkbox"/> Other _____
--	---	---	--

Stories: 1.5 Basement: None Partial Full Dimensions: L _____ x W _____ = Square feet _____

3. Integrity

Location Design Materials Workmanship Setting Feeling Association

4. Function

Historic Use: Agriculture Commerce/trade Defense Domestic Educational Government Healthcare
 Industry/processing Recreation/culture Religious Social Other
Current Use: Agriculture Commerce/trade Defense Domestic Educational Government Healthcare
 Industry/processing Recreation/culture Religious Social Vacant Other

5. Architectural History

Architect: C. G. Lancaster Builder: C. G. Lancaster
Construction date: 1901 [X] Actual [] Estimated Source: Atlas Data
[] Additions/modifications, specify dates:
[] Relocated, specify former location and reason:
Other associated contexts and information of interest:

6. Archeology Ground

[X] Original state [] Disturbed Explain
Is a State Archeological Survey Form available for this site? [] Yes [X] No [] Not known
Details:

7. Other Information

Is prior documentation available for this resource? [] Yes [X] No [] Not known Type: [] HABS [] Survey [] Other
Details:

Accessible to the public: [X] Yes [] No [] Not known Possible threat(s): [] None [] Damage (i.e. natural disaster) [] Neglect
[] Development [] Major alteration [] Relocation [] Other * Note: Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: Year: Map scale:
UTM zone: Easting: 371637 Northing: 3601426
Legal description (Lot/Block): 15
Addition: Year of addition:

9. Significance

Applicable National Register (NR) criteria:

- [] A. Associated with events that have made a significant contribution to the broad pattern of our history;
[] B. Associated with the lives of persons significant in our past;
[X] C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;
[] D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance:

Period(s) of significance: 1900 - 1924

Level of significance: [X] National [X] State [] Local

Possible NR district: [] Yes [] No Is property contributing? [] Yes [] No

10. Priority (See manual for definitions.) [] High [] Medium [] Low

Explain

Questions?

Contact survey coordinator
History Programs Division, Texas Historical Commission
at 512/463-5853 or history@thc.state.tx.us.



TEXAS HISTORICAL COMMISSION

The State Agency for Historic Preservation

www.thc.state.tx.us