City of Nacogdoches Historic Survey Form New New Delete Find

Name jms_301 N. Lanana	Commercial Types	Non-House Date/Vernacular Date
Address 301 N. Lanana Torn Down Recorded by Misty Date Surveyed 8/2/2011 Overall Condition	☐ One-Part C. Block ☐ Temple Front ☐ Two-Part C. Block ☐ Temple Front ☐ Enframed Window Wall ☐ Enframed Block ☐ Stacked Vertical Block ☐ Central Block with Wings ☐ Two-Part Vertical Block ☐ Arcaded Block ☐ Three-Part Vertical Block ☐ Mix	☐ 1. 1820-1865 ☐ 2. 1865-1900 ☐ 3. 1900-1929 ☐ 4. 1929-1945 ☐ 5. 1945-1980 ☐ 6. 1980-today
Roof Type Gable Shed Dormers - Gable Hipped Flat Dormers - Hipped Gambrel Other Dormers - Shed Roof Materials	Agricultural Mfg/Industrial Religious Social State Marker Civic/Government Other Marker Transportation Domestic Parks/Gardens/Plantings	Outbuildings Garage Shed Barn Other Other Chimney
Wood shingles	Educational Local Marker Recreational/Cultural Hall-and-parlor (1story) Shotgun (1 story) Massed side-gable (1) Massed gable-front (1) Town house (2 story) Front-facing	Porch t (2 story)
Wall Facade ☐ Stucco ☐ Other ☐ Number of bays	☐ Four-square (1 story) ☐ Box house (2 story) ☐ 01. Sp. Colon. 1565-1821 ☐ 14. Tudor Rv. 1890s-1940s ☐ 27.	g U or H (1) Internat. 1925-today
Stone Vinyl Siding Terracota Brick Fieldstone V. Awning(s) Log Wood Siding Metal Wood Shingle Numbers of bays 1 2 3 4 5 Other	03. Greek Rev. 1820-1860	Minimal Trad. 1935-60 A-Frame 1930s-present Sm. Ranch 1946-1980 Lg. Ranch 1946-1980 Split-L 1955-1980 Contemp. 1940-1980 Shed 1960-today
Wall Condition ☐ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Bad	☐ 10. RRoman R 1870s-1890s ☐ 23. Craftsman 1900-1930 ☐ 36.	Neoeclect 1965-today Prefab H 1940s-1950s Mobile H 1945-today