

Zion Hill Historic District - Conditions Survey Form



807 Ernest

Historic Function:

- Domestic
- Religious
- Abandoned
- Vacant

Foundation Type:

- Pier & Beam
- Slab

Foundation Material:

- Wood Blocks
- Brick
- Concrete Blocks

Foundation Details:

- Skirtwall (plywood)
- Watertable

Structural Type:

- Wood Frame

Roof Type:

- Front Gabled
- Side Gabled
- Cross Gabled
- Hipped
- Hipped w/Gables
- Pyramidal
- Shed

Roof Materials:

- Composition Shingles
- Wooden Shingles
- Corrugated Metal

Roof Details:

- Extended Box Eaves
- Exposed Rafter Ends
- Triangular Kneebrace
- Bargeboards
- Fascia Board
- Gabled Dormers
- Hipped Dormers
- Pent Roof

Chimney Type:

- Interior
- Exterior

Chimney Materials:

- Brick
- Stone

Chimney Location:

- Ridge
- Slope
- Gable End

No. of Porch Bays

ONE

Porch Type:

- Integral
- Full Width
- Partial Width

Porch Roof:

- Shed
- Hipped
- Gabled

Porch Supports:

- Square Posts
- Turned Posts
- Tapered Box
- Box Columns
- Brick Pedestals
- Wood Pedestals
- Brackets
- Wrought Iron

Porch Details:

- Concrete Floor
- Wood Floor
- Turned-Wd. Balustrade
- Squared-Wood

Exterior Walls

- Wood - Clapboard
- Wood - Novelty
- Wood - Drop Siding
- Wood - Board & Batten
- Plywood
- Cementitious Asbestos
- Aluminum Siding
- Synthetic

Window Type:

- Double Hung
- Casement
- Fixed

Number of Window Lights:

4 X 4

Window Materials:

- Wood Sash
- Metal Sash

Window Details:

- Shutters
- Cornice

Door Type:

- Single
- Double

Door Materials:

- Two Singles
- Wood
- Aluminum

Door Details:

- Transom
- Sidelights
- Paneled
- Glazing

Alterations:

- Siding
- Porch
- Window
- Doors
- Additions

Outbuildings:

- Garage
- Shed
- Other

Other Noteworthy Features SQUARE ATTIC / GABLE VENT

Notes: GOOD CONDITION / WELL MAINTAINED

- Conditions Code: 1. Good/Original 2. Fair/Original 3. Poor/Original 4. Good/Replacement
5. Fair/Replacement 6. Poor/Replacement 7. Removed

Zion Hill Historic District - Conditions Survey Form



808 Ernest

Historic Function:

- Domestic
- Religious
- Abandoned
- Vacant

Foundation Type:

- 2 Pier & Beam
- Slab

Foundation Material:

- Wood Blocks
- 2 Brick
- Concrete Blocks

Foundation Details:

- 6 Skirtwall
- Watertable

Structural Type:

- 1 Wood Frame

Roof Type:

- 2 Front Gabled
- Side Gabled
- Cross Gabled
- Hipped
- Hipped w/Gables
- Pyramidal
- Shed

Roof Materials:

- Composition Shingles
- Wooden Shingles
- 5 Corrugated Metal

Roof Details:

- Extended Box Eaves
- 2 Exposed Rafter Ends
- Triangular Kneesbrace
- Bargeboards
- Fascia Board
- Gabled Dormers
- Hipped Dormers
- Pent Roof

Chimney Type:

- Interior
- Exterior

Chimney Materials:

- Brick
- Stone

Chimney Location:

- Ridge
- Slope
- Gable End

No. of Porch Bays

ONE

Porch Type:

- 2 Integral
- Full Width
- Partial Width

Porch Roof:

- Shed
- Hipped
- Gabled

Porch Supports:

- 2 Square Posts
- Turned Posts
- Tapered Box
- Box Columns
- Brick Pedestals
- Wood Pedestals
- Brackets
- Wrought Iron

Porch Details:

- Concrete Floor
- 3 Wood Floor
- Turned-Wd. Balustrade
- Squared-Wood

Exterior Walls

- Wood - Clapboard
- Wood - Novelty
- 2 Wood - Drop Siding
- Wood - Board & Batten
- Plywood
- Cementitious Asbestos
- Aluminum Siding
- Synthetic

Window Type:

- 2 Double Hung
- Casement
- Fixed

Number of Window Lights:

4x4

Window Materials:

- 2 Wood Sash
- Metal Sash

Window Details:

- Shutters
- Cornice

Door Type:

- Single
- Double

Door Materials:

- 2 Two Singles
- Wood
- Aluminum

Door Details:

- Transom
- Sidelights

- 2 Paneled
- Glazing

Alterations:

- Siding
- Porch
- Window
- Doors
- Additions

Outbuildings:

- Garage
- Shed
- Other

Other Noteworthy Features _____

Notes: _____

Conditions Code: 1. Good/Original 2. Fair/Original 3. Poor/Original 4. Good/Replacement
5. Fair/Replacement 6. Poor/Replacement 7. Removed

Zion Hill Historic District - Conditions Survey Form



812 Ernest

Historic Function:

- Domestic
- Religious
- Abandoned
- Vacant

Foundation Type:

- Pier & Beam
- Slab

Foundation Material:

- Wood Blocks
- Brick
- Concrete Blocks

Foundation Details:

- Skirtwall
- Watertable

Structural Type:

- Wood Frame

Roof Type:

- Front Gabled
- Side Gabled
- Cross Gabled
- Hipped
- Hipped w/Gables
- Pyramidal
- Shed

Roof Materials:

- Composition Shingles
- Wooden Shingles
- Corrugated Metal

Other Noteworthy Features

Notes:

Roof Details:

- Extended Box Eaves
- Exposed Rafter Ends
- Triangular Kneebrace
- Bargeboards
- Fascia Board
- Gabled Dormers
- Hipped Dormers
- Pent Roof

Chimney Type:

- Interior
- Exterior

Chimney Materials:

- Brick
- Stone

Chimney Location:

- Ridge
- Slope
- Gable End

No. of Porch Bays

2

Porch Type:

- Integral
- Full Width
- Partial Width

Porch Roof:

- Shed
- Hipped
- Gabled

Porch Supports:

- Square Posts
- Turned Posts
- Tapered Box
- Box Columns
- Brick Pedestals
- Wood Pedestals
- Brackets
- Wrought Iron

Porch Details:

- Concrete Floor
- Wood Floor
- Turned-Wd. Balustrade
- Squared-Wood

Exterior Walls

- Wood - Clapboard
- Wood - Novelty
- Wood - Drop Siding
- Wood - Board & Batten
- Plywood
- Cementitious Asbestos
- Aluminum Siding
- Synthetic

Window Type:

- Double Hung
- Casement
- Fixed

Number of Window Lights:

4x4

Window Materials:

- Wood Sash
- Metal Sash

Window Details:

- Shutters
- Cornice

Door Type:

- Single
- Double
- Two Singles

Door Materials:

- Wood
- Aluminum

Door Details:

- Transom
- Sidelights
- Paneled
- Glazing

Alterations:

- Siding
- Porch
- Window
- Doors
- Additions

Outbuildings:

- Garage
- Shed
- Other

Conditions Code:

- 1. Good/Original
- 2. Fair/Original
- 3. Poor/Original
- 4. Good/Replacement
- 5. Fair/Replacement
- 6. Poor/Replacement
- 7. Removed