City of Nacogdoches Historic Survey Form

T New A Delete W Find		
Name jms_304NChurch	Commercial Types	Non-House Date/Vernacular Date
Address 304 N. Church Recorded by Misty Date Surveyed 8/2/2011 Overall Condition	One-Part C. Block Temple Front Two-Part C. Block Temple Front Enframed Window Wall Enframed Block Stacked Vertical Block Central Block with Wings Two-Part Vertical Block Arcaded Block Three-Part Vertical Block Mix	1. 1820-1865 2. 1865-1900 3. 1900-1929 4. 1929-1945 5. 1945-1980 6. 1980-today
Roof Type Gable Shed Dormers - Gable Hipped Flat Dormers - Hipped Gambrel Other Dormers - Shed Roof Materials Wood shingles Tile Other Composition shingles Metal Roof Condition Excellent Good Fair Poor Bad		t (2 story) re (2 story) st-and-wing (2)
Wall Facade Stucco Other Number of bays Stone Vinyl Siding Terracota Brick Fieldstone V. Awning(s) Log Wood Siding Metal Wood Shingle Numbers of bays 1 2 3 4 5 Other Wall Condition Excellent Good Fair Poor Bad	Four-square (1 story)	Internat. 1925-today Minimal Trad. 1935-60 A-Frame 1930s-present Sm. Ranch 1946-1980 Lg. Ranch 1946-1980 Split-L 1955-1980 Contemp. 1940-1980 Shed 1960-today Neoeclect 1965-today Prefab H 1940s-1950s Mobile H 1945-today