City of Nacogdoches Historic Survey Form New New Delete Find

Thew Delete San Thiu		
Name Individual Properties	Commercial Types Non-House Date/Vernacular	Date
Address 410 Bremond Street Recorded by Norris Nelson Date Surveyed 8-8-2011 Overall Condition	□ One-Part C. Block□ Temple Front□ 1. 1820-1865□ Two-Part C. Block□ Temple Front□ 2. 1865-1900□ Enframed Window Wall□ Enframed Block□ 3. 1900-1929□ Stacked Vertical Block□ Central Block with Wings□ 4. 1929-1945□ Two-Part Vertical Block□ Arcaded Block□ 5. 1945-1980□ Three-Part Vertical Block□ Mix□ 6. 1980-today	
Roof Type Gable Shed Dormers - Gable Hipped Flat Dormers - Hipped Gambrel Other Dormers - Shed Roof Materials Wood shingles Tile Other Composition shingles Metal Roof Condition Excellent Good Fair Poor Bad Wall Facade		gs Shed Other
Stucco Other Number of bays Stone Vinyl Siding Terracota Brick Fieldstone V. Awning(s) Log Wood Siding Metal Wood Shingle Numbers of bays 1 2 3 4 5 Other Wall Condition Excellent Good Fair Poor Bad	01. Sp. Colon. 1565-1821	