

HISTORIC RESOURCES SURVEY FORM

1. Identification

County Harrison City MarshallCurrent name Old Patillo House Historic name Patillo HouseAddress 510 N. Bolivar St.Owner/address N/A

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☒ RTHL ☐ HTC ☐ SAL ☐ Local ☐ OtherRecorded by: Natalie Bach-Preather Date recorded: 1/12/13General architectural description 1-story hand-made brick with four 4/4 windows and a single-door primary entrance.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

- | | | | | |
|---|--|---|---|---|
| ☐ Log Traditional | ☐ Shingle | ☐ Gothic Revival | ☐ Pueblo Revival | ☐ International |
| ☒ Greek Revival | ☐ Romanesque Revival | ☐ Tudor Revival | ☐ Spanish Colonial | ☐ Post-war Modern |
| ☐ Italianate | ☐ Folk Victorian | ☐ Neo-Classical | ☐ Prairie | ☐ Ranch Style |
| ☐ Second Empire | ☐ Colonial Revival | ☐ Beaux Arts | ☐ Craftsman | ☐ Commercial Style |
| ☐ Eastlake | ☐ Renaissance Revival | ☐ Mission | ☐ Art Deco | ☐ No Style |
| ☐ Queen Anne | ☐ Exotic Revival | ☐ Monterey | ☐ Moderne | ☐ Other _____ |

Structural Details:

Roof Type: ☒ Gable ☐ Hipped ☐ Gambrel ☐ Shed ☐ Flat w/parapet ☒ Dormers: ☒ gable ☐ hipped ☐ shed ☐ Other _____	Wall Facade: ☐ Number of bays _____ ☐ Stucco ☐ Stone ☒ Brick ☐ Wood shingle ☐ Log ☐ Terra Cotta ☐ Metal ☐ Siding, type _____ ☐ Fieldstone veneer ☐ Awning(s) ☐ Other _____	Windows: ☒ Fixed ☐ Wood sash ☐ Double hung ☐ Casement ☐ Aluminum sash ☐ Decorative screenwork ☐ Other _____	Plan: ☐ L-plan ☒ 2-room ☐ T-plan ☐ Open ☐ Modified L-plan ☐ Center passage ☐ Bungalow ☐ Shotgun ☐ Irregular ☐ Four Square ☐ Rectangular ☐ Other _____
Roof Materials: ☐ Wood shingles ☐ Tile ☒ Composition shingles ☐ Metal ☐ Other _____	Chimneys: ☐ Specify number(s) _____ ☐ Interior ☒ Exterior ☒ Brick ☐ Stone ☐ With corbelled caps ☐ Stuccoed ☐ Other _____	Doors: ☒ Single-door primary entrance ☐ Double-door primary entrance ☐ With transom ☐ With sidelights ☐ Other _____	Foundation: ☐ Slab ☒ Pier and beam ☐ Perimeter wall ☐ Other _____
Construction: ☐ Frame ☐ Adobe ☒ Solid brick ☐ Solid stone ☐ Other _____	Porches: ☒ Shed roof ☐ Hipped roof ☐ Gable roof ☐ Inset ☒ Wood posts ☐ Brick piers ☐ Box columns	☐ Classical columns ☐ Tapered box supports ☐ Fabricated metal ☐ Spindlework ☐ Jig-sawn trim ☐ Other _____	

Stories: 1 Basement: ☒ None ☐ Partial ☐ Full Dimensions: L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare

☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare

☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: N/A Builder: N/A

Construction date: _____ ☐ Actual ☐ Estimated

Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☒ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☒ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known Type: ☐ HABS ☐ Survey ☐ Other _____

Details: _____

Accessible to the public: ☒ Yes ☐ No ☐ Not known Possible threat(s): ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect

☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____ * Note: Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: _____ Year: _____ Map scale: _____

UTM zone: 15 Easting: 371730 Northing: 3602186

Legal description (Lot/Block): _____

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☒ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Area of significance: Built for William Patillo, the teaming and transport contractor
for Trammel's Trace

Period(s) of significance: 1846

Level of significance: ☐ National ☒ State ☒ Local

Possible NR district: ☐ Yes ☒ No Is property contributing? ☐ Yes ☒ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

Questions?

Contact survey coordinator

History Programs Division, Texas Historical Commission

at 512/463-5853 or history@thc.state.tx.us.



TEXAS
HISTORICAL
COMMISSION

The State Agency for Historic Preservation

www.thc.state.tx.us